

TO BE FILLED BY THE INSPECTING OFFICER
(Assistant Engineer / Assistant Executive Engineer)

Name of School Dawn Public School, Edakkara.

1. Name of the Officer Shabeela K, Assistant Engineer

2. Location Malakkulathur, Kozhikode.

3. Period for which the certificate is issued 2021 - 2022.

4. Types of building Permanent RCC two storied building.

GF - 6.10 x 6.50 x 3.60 m ff (sheet roof)

5. Nature of defect if any 7.80 x 6.20 x 3.60 m 7.00 x 6.10 x 3.60

7.80 x 6.20 x 3.60 m 6.60 x 6.10 x 3.60

a) Foundation and basement 6.40 x 3.00 x 3.60 m 6.60 x 6.10 x 3.60

7.50 x 6.50 x 3.60

b) Superstructure Nil 7.50 x 6.00 x 3.60

7.50 x 6.00 x 3.60

c) Doors and windows Nil 7.70 x 6.00 x 3.60

4.30 x 6.00 x 3.60

d) Wood work wrought and put up Nil

e) Roof Nil

f) Flooring Nil

g) Miscellaneous (Cracks if any) Nil

6. Any major defects noticed which will render the building unsafe in any manner Nil

7. Whether maintenance work have been done properly Yes

8. Whether the structure is sound or not for conducting classes. Yes, the structure is sound for conducting classes under normal wind and weather conditions.

Note: 1 The Stability of the structure should be examined also with reference to location altitude intensity of wind exposure to flood etc.

2 Any additional observation deemed necessary for the Certificate, may be furnished separately with the Certificate.

Certified that the School was inspected by me on 25-09-2021 and found to be, fit / unfit to conduct classes for the period for the reasons stated above.

Place: Malakkulathur

Date: 25-09-2021



ASSISTANT ENGINEER
LSGD SECTION
MALAKKULATHUR GRAMPANCHAYATH